

NARRATIVE

Vehicle 1 was speeding while traveling south on a straightaway portion of Miller Road. Vehicle 1 attempted to turn at the intersection of Miller Road and Arrow Point Drive NE while driving too fast in wet road conditions. As a result, Vehicle 1 went off the roadway past the stop sign at the intersection into the trees. Vehicle 1 collided with a tree south of the Arrow Point Drive NE road edge, which caused damage to the front end and underside of the vehicle.

