

NARRATIVE

Unit 1 was parked on the dirt shoulder of Miller Road northbound approximately 150 feet north of Bergman Road. Unit 1 was attempting to back up southbound using the shoulder on Miller to have enough space to turn into the roadway. The shoulder of Miller was soft and muddy and Unit 1 rolled over on its side down an embankment.

