

## **NARRATIVE**

The operator of an Amazon delivery vehicle was at the residence to make a delivery. The driver reported they thought there was adequate clearance to drive under an exposed beam, drive through, driveway. As they slowly moved into that space, they felt a bump at the front of the vehicle. They then began to back up and heard a crack, then stopped.

The driver had knocked the beam loose and dislodged the mounting hardware and pulled the beam 6' to the rear when backing up. The beam did not detach from the house, only the outlying support structure.

