

## NARRATIVE

Vehicle 1 was travelling southbound on Highway 305 in a 35-mph construction zone. A witness stated the PT Cruiser went straight away instead of following the first curve of the construction zone, hitting and destroying two orange barrel cones and a pile of lumber head on in the construction zone. Two pieces of lumber were destroyed. The PT Cruiser was leaking a significant amount of antifreeze and left a long trail of antifreeze on the scene. Vehicle 1 then proceeded to back out of the construction zone and continue SB on highway 305.

