

## NARRATIVE

Unit 1, a [REDACTED] dump truck towing a rollaway trailer, was travelling southbound on State Route (SR) 305 just south of Reitan Road. Unit 1's driver looked in his left side mirror and observed that the trailer tongue was pointed toward the center of the roadway. The trailer was partially dragged in the southbound shoulder of SR 305 before it collided with a speed-limit radar sign just north of the construction site at SR 305 and Ada's Will, causing minor damage to the sign's taillights. The driver was able to safely stop and disconnect before manually moving the trailer's tongue safely out of the roadway.

Upon further inspection, it was discovered that the trailer tongue's connection to the trailer's chassis had partially failed due to corrosion.

[REDACTED] conducted an on-site weld repair of the trailer and safely removed the trailer from the roadway.

I also notified the construction company about the damage to the sign.

