Unit 1 was in the southbound ferry lane (2 of 2) on State Route (SR) 305 at Winslow Way. Unit 2 was southbound in the turn lane (1 of 2) on SR 305 preparing to turn right (westbound) onto Winslow Way.

Unit 2 had a green light to turn right and began to turn onto Winslow Way. Unit 1's light to proceed toward the ferry was red, but began to proceed into the intersection. Unit 2 did not have time to stop and scraped the side of Unit 1. The driver of Unit 1 was issued a notice-of-infraction for failure-to-obey a traffic signal.

