

NARRATIVE

Vehicle #1 had just completed a left turn from eastbound Madison onto northbound SR-305. The driver of #1 told me he shifted into second gear and began to accelerate. As this input was occurring the back end of the truck broke free and the truck began to yaw in a counterclockwise direction. The truck left the roadway, back end first, coming to rest against brush/tree.

Driver #1 did not claim any injuries. The damage to the truck was limited to the back of the cab, including shattering the rear window. The driver was given the case number to this event and the vehicle was released to him.

