

NARRATIVE

Veh 1 was traveling SB on Fletcher Bay Rd. approaching the intersection of Bucklin Hill Rd. On scene I located tire marks that showed the vehicle slowly drift off the road and into a power pole causing reportable damage to both the vehicle and the power pole. Driver stated when contacted that he fell asleep at the wheel and crashed.

