Unit 1 was actively making deliveries on Ward Avenue. Unit 2 was travelling southbound on Ward

Avenue toward Eagle Harbor Drive, stopped behind Unit 1. Unit 1 began backing and did not see Unit 2. Unit 1 struck Unit 2's front end. The driver of Unit 1 was cited for improper backing.

