

NARRATIVE

Vehicle 1 was traveling northbound on Ferncliff Ave approaching the 90 curve in the road that changed into westbound Lofgren Rd. Vehicle 1 approached the curve with too much speed and the driver lost control. Vehicle 1 skidded into the ditch along the north side of westbound Lofgren Rd. Vehicle 1 collided with the ditch with sufficient force to turn the vehicle around approximately 180 degrees and to flid Vehicle 1 onto its roof.

