

NARRATIVE

Vehicle 1 was travelling east on Foster RD approaching the corner where it turns north. Foster also heads south from this corner and there is a shared driveway that goes east.

The driver of Vehicle 1 failed to notice the road turned in time due to the downpour of rain and the street not being illuminated. The driver attempted to brake and turn the vehicle and put it into a slide, colliding with a bank of mailboxes to 5769, 5771, 5777, 5780, and 5784 Foster RD.

The driver and occupants were unharmed, and called the registered owner to determine what to do. The registered owner and parent of the driver told them to contact their insurance company. The driver did so and their insurance arranged a tow for them. The driver waited on scene for approximately two hours but the tow never came, they then left with a friend.

I advised the driver to contact police next time he is involved in a collision.

The vehicle was towed from the scene by Kitsap Towing with moderate front end damage.

The mailboxes were unscathed and the owners replaced the post they were attached to.

