

## NARRATIVE

Vehicle 1 was traveling west on Eagle Harbor DR. The driver of Vehicle says he had a coughing fit which caused him to veer off the right shoulder. Vehicle 1 entered a roadside ditch and traveled approximately twenty yards along a wooden fence.

The wooden fence and shrubbery were damaged by the impact.

Vehicle 1 sustained moderate damage to the front right corner.

Both side airbags deployed on Vehicle 1.

The driver of Vehicle 1 claimed no injury at this time.

