

NARRATIVE

Vehicle 1 was making a left turn from west to North from Baker Hill Rd onto Lynwood Center Rd while traveling at a speed too fast for conditions. Vehicle 1 slid through the intersection and struck a 35 MPH speed limit sign on the northbound shoulder of Lynwood Center Rd, breaking it off at the bottom. The vehicle slid into the ditch on the northbound shoulder after striking the sign and came to a stop.

