Olympic Drive SE. Unit 2 was also headed southbound on State Route 305 through the intersection of Winslow Way E onto Olympic Drive SE. Unit 1 was in the lefthand lane marked for left turns or local traffic/transit straight. Unit 2 was in the righthand lane marked for right turns or traffic straight through to the ferry. Both units had a green traffic signal. Unit 1 proceeded through the intersection and moved into Unit 2's lane of travel, causing Unit 2 to collide with Unit 1, Unit 1 had damage to the entire right side of the vehicle. Unit 2 had damage to the entire front side and front driver's side of the vehicle.

NARRATIVE

