DRV 1 stated he was traveling northbound on Sportsman Club RD approaching the intersection with NE Wardwell RD when an animal ran into the roadway. DRV 1 state he swerved to avoid the animal

stated they happened because he had got smacked into his head. DRV 1 declined aid during the 911 call, and declined aid when I asked him if he needed it on scene.

VEH 1 had the side curtain airbags deployed. VEH 1 sustained damage to the front left wheel rendering the vehicle unable to be driven. VEH 1's damage was above the reportable threshold.

and drove into the ditch on the west side of the road. DRV 1 had small scrapes on his face, and

NARRATIVE

I took photos of VEH 1 and submitted them to Evidence.com.

DRV 1 was attempting to contact his boss, who is the RO for VEH 1. I advised DRV 1 that if the RO did not want to make towing arrangements, to contact me so I could return to the scene to facilitate a tow.

DRV 1 was unable to identify what kind of wildlife had walked into the roadway, I have used an emu to represent the unknown wildlife in the diagram.

