

NARRATIVE

Unit #1 was NB in the northbound outside lane and made a U-Turn to get in the ferry line in front of unit #2, a motorcyclist NB in the northbound inside lane. The motorcycle impacted #1 on the driver side and the driver was airlifted to Harborview Hospital. There is no indication of excessive speed or impairment on either party.

