Per the involved parties, Vehicle #1 had just made a right turn onto west bound Madison Ave. As he began to accelerate the rear end of the vehicle lost traction on the damp payement and began to yaw.

The driver said that he overcorrected causing the vehicle to yaw more wildly. The front driver's side

impacted into Vehicle #2.

NARRATIVE

The driver of Vehicle #2 saw the truck round the corner and begin to slide. She tried to steer her car to the right but the truck graved the rear driver's side fender causing scuffing on the lower part of the fender.

