

## NARRATIVE

The driver of vehicle 1 became distracted and failed to negotiate the curve of the roadway. Vehicle 1 veered off the roadway and into a ditch. The vehicle struck and destroyed a wooden road sign and came to a rest after having both front airbags deploy. The driver was not injured. Damage threshold met on vehicle 1. The vehicle was able to be removed from the scene without tow.

