

NARRATIVE

Unit 1 was travelling northbound on State Route (SR) 305 just north of the High School Road Intersection. Unit 1's driver oversteered and lost traction, causing the vehicle to go off of the road and into a ditch before coming to a stop in the brush on the northbound side of SR 305. Unit 1's driver did not have any apparent injuries. The vehicle's front side airbags deployed in the crash, and the vehicle suffered significant damage to its front end.

