Unit 1 (commercial bucket truck with trailer) did not observe unit 2 stopped for traffic. Unit 1 attempted

to use the shoulder to avoid a collision with the rear of unit 2 but was unable due to its size. Unit 1 collided with the rear passenger side of the vehicle and continued down the side of the vehicle causing reportable damage and a flat tire. No injuries. Damage threshold met.

