

NARRATIVE

Unit 1 was driving northbound on State Route 305 on Bainbridge Island just south of Day Road. Unit 2 was stopped for traffic.

Unit 1 drove onto the shoulder and collided with the rear of Unit 2. The driver of Unit 1 reversed to separate the two vehicles, put the vehicle back into drive, and inadvertently struck Unit 2 a second time. Unit 1 had substantial damage to its left front fender and front bumper. Unit 2 had significant damage to its right rear fender and was subsequently towed from the scene.

The driver of Unit 2 complained of minor neck and back pain but was not evaluated by aid on scene.

