

## NARRATIVE

Vehicle 1 was traveling south on Sportsman club RD, approaching the intersection with New Brooklyn RD. Vehicle 2 was traveling east on New Brooklyn RD, approaching the same intersection. The Sportsman Club/New Brooklyn intersection is controlled with stop signs and a flashing red signal. Vehicle 2 came to a stop at the intersection, and waited for an uninvolved vehicle to enter the intersection from the north. After that vehicle had passed through the intersection, Vehicle 2 entered the intersection to continue east. Vehicle 1, followed the uninvolved vehicle through the intersection, without stopping for the signs or signals. The front right corner of Vehicle 1 collided into the front of Vehicle 2. None of the occupants of either vehicle claimed any injury at this time. Both vehicles were able to leave the scene under their own power. The witness was on foot at the south-east corner of the intersection, and described the collision as I have.

