Unit 1, a garbage truck, was conducting regular trash pickup. The driver of Unit 1 was not yet accustomed to the new equipment on the truck (an automatic arm that picks up the cans and dumps

them into the truck) and forgot to put the arm "in". Unit 1 was travelling westbound on Manitou Bech Drive in the vicinity of the 10000 block and inadvertently struck a legally parked unoccupied vehicle, Unit 2. Unit 1 did not sustain any reportable damage. Unit 2's rear bumper sustained reportable damage. Both vehicles were driveable from scene.

REPORT NO. EF35287 **CASE #** 124001073 DATE AND TIME OF COLLISION 11/06/24 12:00

HUE NOT OBSERVE