

NARRATIVE

Unit #2, a pedalcyclist, was eastbound on the sidewalk on Wyatt at Lovell and turned suddenly into the crosswalk in front of Unit #1. #1 was able to stop just prior to crossing into the crosswalk. #2 was knocked from his bike and had a sore leg. He was seen by Aid and not transported. Damage to #1 consisted of broken headlight lens on the passenger side. Bicycle belonging to Unit #2 was destroyed.

