

## NARRATIVE

Vehicle 1 was traveling northbound on State Route 305 behind Vehicle 2 north of the intersection with Lovegreen Rd. Vehicle 2 was stopped for traffic.

According to the driver of Vehicle 1, the traffic ahead of Vehicle 2 started to accelerate, but Vehicle 2 had not yet. Vehicle 1 started to accelerate and collided with the back of Vehicle 2.

According to the driver of Vehicle 2, Vehicle 2 was stopped and the vehicles ahead of Vehicle 2 were also stopped. Vehicle 1 collided with the back of Vehicle 2.

Both drivers reported that Vehicle 1 rear-ended Vehicle 2.

The driver of Vehicle 2 was transported to the hospital and their vehicle was towed from the scene in their absence.

