


NARRATIVE

VEH 1 was driving westbound on Hidden Cove RD between both ends of Spargur Loop. DRV 1 stated he was adjusting items around the vehicle controls and drifted off the roadway.

DRV 1 sustained two broken teeth but declined medical aid beyond an initial evaluation by Bainbridge Fire medics.

VEH 1 had the right front wheel torn off at the axel due to striking a concrete culvert pipe that was laying parallel to the roadway. VEH 1 tipped over to the left after striking the culvert and having the passenger's side wheels elevated. The culvert sustained a small chip, but remained intact.



NOT TO SCALE