Driver of Unit # 1 is employed as a mechanic and was test driving a vehicle after performing work on

it. He advised that he was exceeding the speed limit when he reported that a vehicle pulled out in front of him, causing him to jerk the wheel left to avoid a collision. Upon turning the wheel back to the right, the turn was overcorrected causing the car to slide sideways off the road and into a mailbox and fence. He advised that prior to the crash the vehicle was mechanically sound, and the there was no indication that the collision was the result of a mechanical failure.

NARRATIVE

