

## NARRATIVE

Unit 1, a white 2022 Toyota Corolla with WA license plate [REDACTED] was travelling Eastbound on Hidden Cove Rd. Unit 2, a dark blue 2022 Ram 2500 with WA license plate [REDACTED] was travelling Southbound on State Highway 305. Unit 1 went to turn Northbound from Hidden Cove Rd on to State Highway 305, causing Unit 2 to collide with Unit 1.

The driver of Unit 1 was transported to St. Michael's Medical Center for complaints of left ear pain and bruising to the left side of their body.

Unit 1 sustained extensive damage to the driver side of the vehicle.

Unit 2 sustained extensive damage to the front end of the vehicle.

Unit 1 cited for failure to yield, to be mailed by court.



Not to Scale

