

NARRATIVE

Vehicle 1 was traveling north on Miller Rd., behind Vehicle 2. As they approached the intersection with Peterson Hill, Vehicle 2 slowed to a stop, intending to make the left turn onto Peterson Hill RD, but waiting for the south bound traffic to break. Vehicle 1 failed to come to a stop, and ollided into the rear left corner of Vehicle 2. Both vehicles sustained moderate damage. The driver of vehicle 1 sustained an injury to his lower lip, and was transported by aid to Saint Michael Medical Center for treatment. Vehicle 1 was not able to leave the scene under its own power, and was impounded with Kitsap Tow. Neither occupant of Vehicle 2 claimed any injury at this time. Vehicle 2 was able to leave the scene under its own power. The driver of Vehicle 1 was cited for not having liability insurance, he was notified of his citation and that it would be mailed to him.

