

NARRATIVE

Unit 1 was proceeding southbound toward the Bainbridge Island Ferry on State Route (SR) 305 just south of Vineyard Lane. Unit 1 did not see stopped traffic in the ferry lane and was exceeding a speed safe relative to the conditions.

Unit 2 was stopped in the ferry queue.

Unit 1 did not have time to stop and collided with the rear end of Unit 2, causing minor damage to both vehicles.

