

NARRATIVE

Vehicle #1 had just stopped at the west bound stop sign at the intersection of SR-305 and Morgan Rd. He checked for northbound traffic and believed that it was clear and began to roll forward to cross SR -305 and access Just-A-Meer, entering the northbound lane of 305. Vehicle #2 was traveling northbound on 305 and saw the Amazon delivery vehicle edging out into the northbound lane. He said that he believed the driver was turning right onto northbound 305. He began to slow but closed the interval and vehicle #1 did not turn right. The vehicles collided with front right corner of #2 striking #1 on the driver's side just behind the driver's door. On impact #2 yawed in a clockwise direction and came to rest next to #2 with both vehicles facing north.

Neither driver was claiming injury. Vehicle #2 had the front right bumper pushed back to a point that it interfered with the travel of the front right tire. The owner of #2, Kitsap Transit, arranged for their own tow truck to respond.

Driver #1 was notified that he would be receiving a Notice of Infraction for failing to yield the right of way. This was due to technical problems with this officers SECTOR system.

Both parties were given the case number to this incident.

