Vehicle 1 was intending to exit the parking lot for 215 Madison Ave S. Vehicle 2 was traveling north on Madfison Ave S. As Vehicle 2 passed the driveway to 215 Madison Ave. S, they slowed as they approached the intersection with Bjune DR. Vehicle 1 pulled left onto north bound Madison Ave S,

NARRATIVE

but did not anticipate Vehicle 2's slowing. Vehicle 1 struck Vehicle 2 with their front right corner. Vehicle 2 sustained moderate damage to their rear end. Vehicle 1 sustained moderate damage to their front right corner. Both vehicles were able to leave the scene under their own power. No occupant of either vehicle claimed any injury. The driver of Vehicle 1 was cited for failing to yield to a motor-vehicle.

