## Driver 1 was traveling westbound on Winslow Way E. Driver 1 made a left turn into a parking spot on Winslow Way E. As Driver 1 turned left into the spot, she turned too wide, causing the front right

corner of her vehicle to collide with the left rear door of Driver 2's vehicle.

There were no reported injuries from either vehicle.

NARRATIVE

Driver 1's vehicle had minor damage to the right-front corner of their bumper. Driver 2's vehicle had a medium sized dent in the left-rear door. Driver 2's vehicle was occupied with driver and a child, restrained in the right-rear seat.



Р

PAGE