

NARRATIVE

Vehicle 1 was traveling east and downhill on HighSchool RD approaching the intersection with Madison Ave, a traffic circle intersection. As Vehicle 1 began to navigate the traffic circle, they lost traction and slid east ward into the northbound Madison yield sign. Vehicle 1 struck the sign with their license plate at low speed, knocking the post over and bending it. Vehicle 1's front right tire struck the curb and deflated.

Vehicle 1 was able to leave the scene under their own power. The driver of vehicle 1 attempted to contact the property owner over the damaged property.

The witness saw the collision as described from their position, yielding on Madison heading north into the roundabout.

