

NARRATIVE

Vehicle 1 was traveling South on Madison Ave approaching the intersection with Wyatt Way. Vehicle 2 was traveling East on Wyatt Way approaching the intersection with Madison Ave.

The intersection is a traffic circle.

Vehicle 2 arrived first and yielded to a vehicle in the circle traveling South.

Vehicle 1 and 2 entered the circle at the same time, Vehicle 1 was carrying speed as they entered because there was no vehicle to yield to at the time. They were going just below the posted speed of 25mph, but above the advisory speed of 5mph for the circle.

Vehicle 1 applied their brakes to avoid colliding with Vehicle 2. As Vehicle 2 rounded the southern edge of the circle they applied their brakes and Vehicle 1, which had just resumed forward travel, collided into Vehicle 2's rear.

Both Vehicles sustained minor damage.

