

## NARRATIVE

Vehicle 2 was following Vehicle 1 eastbound along Winslow Way approaching the intersection with State Route 305 and came to a stop side-by-side at the intersection. The driver of Vehicle 1 reported that Vehicle 2 was tailgating him along Winslow Way and that the driver of Vehicle 2 yelled at him when they stopped at the intersection. This angered the driver of Vehicle 1. Vehicle 2 continued east along Winslow Way past the intersection and Vehicle 1 followed. However, Vehicle 2 slowed to turn into the parking lot at 625 Winslow Way E and Vehicle 1 collided with the back of Vehicle 2.

