
NARRATIVE

fender of Unit 2. Unit 1 had damage to the right front fender and right rear fender. Unit 2 had damage to the right rear fender. Driver 1 said he was driving Unit 1 and admitted to striking the vehicle due to a moving truck being parked across from him which limited space.



PAGE ³ OF ³