

## NARRATIVE

Unit #1 intended to turn left (south) from westbound Wyatt Way onto Grow Avenue. Unit #2 intended to turn left onto Wyatt Way from northbound Grow Avenue. Unit #1 advised that she had the right of way and it was her turn and # 2 pulled out in front of her while she was turning. Unit #2 advised that #1 stopped at the stop sign then turned into her. She advised that she saw what was going to happen and hit her horn. Damage to both vehicles is on driver side front, with the damage to #1 being a longer scrape than on #2 indicating that most likely #2 was stopped at the time of the collision. No witnesses came forward and which vehicle arrived at the intersection first and exact position of # 2 at the time of the collision could not be determined as there was not scuffs visible on the road or debris piles at the location of the collision.

