

## NARRATIVE

Vehicle #1 was moving south on Euclid when it entered the uphill “S-Turn” south of Meigs Rd. Upon entry into the turn the driver and both passengers reported that a deer was in the roadway. The driver maneuvered away from the deer but drifted onto the west grass covered shoulder. He went off the roadway in a yaw, leading with the driver’s side of the car. the shift in the center of gravity of the car caused the leading wheels begin to dig into the soft surface causing the car to roll to the left. All forward progress was stopped when the car struck a tree causing the car to rotate approximately 60 degrees.

