

## NARRATIVE

Unit 1 was traveling Westbound towards Highway 305 on Day Rd E . Unit 1 collided into the back of unit 2, which was stopped at a stop light. Unit 1 applied their breaks going down hill in an attempt to prevent a collision with the vehicle ahead of them. Due to the wet and rainy road conditions unit 1 was unable to stop and prevent the collision. Unit 1 collided into the back of Unit 2. Unit 1 was towed from the scene.

Not to scale

