Vehicle 3.

approaching the traffic signal at the intersection of State Route 305 and Day Rd NE. Vehicle 2 began slowing as they approached the intersection and Vehicle 1 was approximately two to three car lengths behind Vehicle 2. Vehicle 1 attempted to hit the brakes and stated that their brakes started to vibrate (ABS engaging) and were unable to stop as the front end of Vehicle 1 collided with the rear end of Vehicle 2. Vehicle 3 was slowing and coming to a stop in front of Vehicle 2, but the force of the collision pushed Vehicle 2 forward resulting in the front end of Vehicle 2 striking the rear end of

