

NARRATIVE

Vehicle 1 was traveling northbound along Blakely Ave approaching the intersection with Old Mill Rd when a deer ran out into the roadway from the west side of the road in front of Vehicle 1. Vehicle 1 was unable to slow in time to avoid hitting the deer and suffered significant front-end damage to the vehicle.

