

NARRATIVE

Vehicle 1 was parked facing southbound along the south end of the Island Village parking lot. Vehicle 2 was parked facing northbound in a parking spot across the aisle from Vehicle 1. Vehicle 1 began to back out of its space to the west to leave the parking to the east. Vehicle 2 began to back out of its space to the east to leave the parking lot to the west. Vehicle 1 and Vehicle 2 backed into each other in the aisle.

